



GOAT WORKER

STEP ONE

Place the Goat Worker in a convenient working location. Make sure it is level and firmly positioned.



STEP TWO

Place chute on stand. Allow for 1" - 1-1/2" of stand to extend beyond the Goat Worker on both ends.



STEP THREE

Attach the Alley Ramp to the rear of the chute by setting the curved flange on the ramp onto the lip on the rear of Goat Worker stand.



STEP FOUR

Attach Alley Panels with the black (smooth) side facing inward. Use the sliding pins that come attached to the chute to firmly secure the panels.



STEP FIVE

Place end of Alley Ramp over bottom of pendulum gate.



STEP SIX

Attach Alley Panels on each side to rear pendulum gate with corral pins.



YOUR GOAT WORKER IS NOW COMPLETE & READY TO USE!



TARTER
Working Harder Since 1945

WWW.TARTERGATE.COM